

FITNESS CERTIFICATE OF SCHOOL BUILDING

To be filled by the Inspecting Officer (Assistant Engineer)

(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

- 1 Name of the Institution : **Sidhartha central school**
- 2 Name of the Officer : Rachana.V, Assistant Engineer, LSGD Section, Elamadu
Grama Panchayath
- 3 Location with Educational District/SubDistrict : Nettayam, Veliyam , kottarakara
- 4 Classification of Buildings as specified in column for the application for fitness certificate and size :
(i) Permanent Single or multystoried : RCC building (GF&FF) 1x30.85x8.03x3.60m + 9.45x8.13x3.60m (Lshaped building)
(ii) Semi permanent : GI roof shed with false ceiling with 7 classrooms of size (6.10x9.50m Each)
(iii) Temporary shed : Nil
- 5 Period for which certificate is issued : 2026-27 Academic year
- 6 Nature for which certificate is issued : Fitness certificate of School Building
- 7 Nature of Defects if any
 - a. Foundation& Basement : Random Rubble
 - b. Superstructure : Brick Work
 - c. Doors and Windows : Country Wood
 - d. Woodwork wrought and putup : Nil
 - e. Roof : RCC
 - f. Flooring : Tile and Cement Plastered
 - g. Miscellaneous(Cracks) : Nil
- 8 Any major defects noticed which will render the building unsafe in any manner : Nil
- 9 Whether maintenance works have been done properly : Yes
- 10 Whether the structure is sound or not for conducting classes : Structures are sound under normal Wind and Weather conditions


Note 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

Note 2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate

CERTIFICATE

Certified that the School Building was inspected by me on 19/5/2026 and found to be fit to conduct classes for the period 2026-27 for the reasons stated above

Place: Elamadu
Date: 25/5/2026



Signature :
Designation :

Rachana.V

ASSISTANT ENGINEER
LID&EW
Elamadu Grama Panchayat

FITNESS CERTIFICATE OF SCHOOL BUILDING

To be filled by the Inspecting Officer (Assistant Engineer)

(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

- 1 Name of the Institution : **Sidhartha central school**
- 2 Name of the Officer : Rachana.V, Assistant Engineer, LSGD Section, Elamadu Grama Panchayath
- 3 Location with Educational District/SubDistrict : Nettayam, Veliyam , kottarakara
- 4 Classification of Buildings as specified in coloumn for the application for fitness certificate and size :
(i) Permanent Single or multystoried : RCC building (GF&FF) 1x30.85x8.03x3.60m + 9.45x8.13x3.60m (Lshaped building)
(ii) Semi permanent : GI roof shed with false ceiling with 7 classrooms of size (6.10x9.50m Each)
(iii) Temporary shed : Nil
- 5 Period for which certificate is issued : 2026-27 Academic year
- 6 Nature for which certificate is issued : Fitness certificate of School Building
- 7 Nature of Defects if any :
a. Foundation& Basement : Random Rubble
b. Superstructure : Brick Work
c. Doors and Windows : Country Wood
d. Woodwork wrought and putup : Nil
e. Roof : RCC
f. Flooring : Tile and Cement Plastered
g. Miscellaneous(Cracks) : Nil
Any major defects noticed which will render the building unsafe in any manner : Nil
- 8 Whether maintenance works have been done properly : Yes
- 9 Whether the structure is sound or not for conducting classes : Structures are sound under normal Wind and Weather conditions


Note 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

Note 2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate

CERTIFICATE

Certified that the School Building was inspected by me on 19/5/2026 and found to be fit to conduct classes for the period 2026-27 for the reasons stated above

Place: Elamadu
Date: 25/5/2026



Signature :
Designation :

Rachana.V

ASSISTANT ENGINEER
LID&EW
Elamadu Grama Panchayat

10. Transformers (if nearby) fenced properly ☐ ☐
11. No exposed or hazardous electric posts/ electric wires near school. ☐ ☐
12. Fire extinguisher installed ☐ ☐


The inspecting officer may offer remarks regarding item 10 and 11. The head of institution shall rectify the defects and obtain NOC from KSEB in cases pertaining to Items 10 and 11.

HEALTH AND SANITATION

13. Adequate, clean, ventilated toilets with running water ☒ ☐
14. Classrooms, common areas and kitchen are clean ☒ ☐
15. First aid kit available ☒ ☐
16. Overgrown vegetation/garbage removed from School premises ☒ ☐
17. Rodent control measures are in place ☒ ☐

Items 13 to 17 are to be certified by the Health staff (HI/H.S) of the concerned Local Body.

Signature & Seal of School Principal/HM:



Siddhartha Central School
Ambalamkunnu

Signature & Seal of Health inspector :



Signature & Seal of Assistant Engineer, LSGD:

HEALTH INSPECTOR
P.H.C ELAMADU
DEPARTMENT OF HEALTH SERVICE
GOVERNMENT OF KERALA

Inspection Date:-----;